



7500 JJ



7501 JJ



7502 JJ



7503 JJ



7504 JJ



7505 JJ



7506 JJ



Danger

7540 KJ




Danger
Unmanned
machinery space
machinery may start
without warning

7542 KJ



Danger
Battery
charging

7543 KJ



Danger
Low
oxygen level

7544 KJ



Danger
You are entering
a CO₂ protected
area

7545 KJ



Danger
Moving
machinery

7546 KJ



Danger
Under
maintenance

7547 KJ



Danger
Overhead
working

7548 KJ



Caution
Out of order

7566 KJ



Danger
Men working
below

7567 KJ



Warning
Hazardous
area

7549 KJ



Warning
Insulate before
removing
guards

7550 KJ



Danger
Dust hazard

7551 KJ



Danger
Asbestos

7554 KJ



Danger
Solvents

7555 KJ



Warning
Motor starts
and stops
automatically

7557 KJ



Caution
Vehicles

7560 KJ



Caution
Exhaust
fumes

7561 KJ



Caution
Steep stairway
use handrails

7624 KJ



Danger
Hot surface

7579 KJ



Danger
Hot

7569 KJ



Caution
Slip
hazard

7572 KJ



Caution
Wet deck

7573 KJ



Caution
Slippery
surface

7574 KJ



Warning
Mind your
head

7570 KJ



Danger
Petroleum
vapour

7580 KJ



Caution
Explosion
risk

7581 KJ



Caution
Explosion
gases

7582 KJ



Danger
Explosive
material

7583 KJ



Danger
Compressed
gases

7584 KJ



Danger
Compressed
oxygen

7585 KJ



Danger
Acid

7590 KJ



Danger
Battery acid

7591 KJ



Danger
Corrosive
substance

7596 KJ



Danger
Caustic

7597 KJ